GREENPEACE COAL ASH SITE COMPILATION - OCT 2010

	Ī		1	1	ĺ	1	ĺ	
Power Company	Parent Company	Ash Location	Associated Power Plant	City	State	Reference	Additional Info	Additional Info
Indianapolis Power & Light	AES Corp.	Petersburg Generating Station Ash Ponds	Petersburg Generating Station	Petersburg	IN	EPA Potential Damage Case	http://www.sourcewatch.or	http://carma.org/plant/d
AES Corporation	AES Corporation	Cayuga Coal Ash Disposal Landfill	Cayuga Generation Plant	Lansing	NY	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	http://carma.org/plant/d
Creative Resources	AES Corporation	Creative Resources Weber Ash Disposal Site		East Vestal	NY	EPA Potential Damage Case		
Allegheny Energy Supply Co	Allegheny Energy	Hatfield's Ferry Power Station	Hatfield's Ferry Power Station	Masontown	PA	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	http://carma.org/plant/d
<u> </u>	<u> </u>	Mitchell Power Station (Formerly West Penn Power				<u> </u>		, , , , , , , , , , , , , , , , , , ,
Allegheny Energy Supply Co	Allegheny Energy	Co.)	Mitchell Power Station Pleasants Power Station	Courtney	PA	EIP Damage Case - Feb 2010	http://www.sourcewatch.or	http://carma.org/plant/d
Monongahela Power Co	Allegheny Energy	Pleasants Power Station	(combined with the auxillary Willow Island Power Station	Willow Island	WV	EPA High Hazard Potential	http://www.sourcewatch.or	http://carma.org/plant/d
Interstate Power and Light	Alliant Energy	Lansing Power Station	Lansing Power Station	Lansing	IA	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	
Wisconsin Power and Light	Alliant Energy	Columbia Energy Center	Columbia Energy Center	Pardeeville	WI	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	http://carma.org/plant/d
Wisconsin Power & Light	Alliant Energy	Rock River Ash Disposal Facility	Rock River Generating Station (no longer coal-powered, now uses natural gas)	Beloit	WI	EPA Potential Damage Case	http://www.sourcewatch.or	http://carma.org/plant/d
Wisconsin Power & Light	Alliant Energy	Edgewater 1-4 Ash Disposal Site	Edgewater Generating Statio	Sheboygan	WI	EPA Potential Damage Case	http://www.sourcewatch.or	http://carma.org/plant/d
Wisconsin Power & Light	Alliant Energy	Nelson Dewey Ash Disposal Facility	Nelson Dewey Generating Station Slag Pond	Cassville	WI	EPA Proven Damage Case	http://www.sourcewatch.or	http://carma.org/plant/d
Ameren Energy Resources Generating				_				
Company	Ameren Corp	Duck Creek Station	Duck Creek Station	Canton	IL	EPA Potential Damage Case	http://www.sourcewatch.or	
AmerenEnergy Resources Gen Co	Ameren Corp	Hutsonville Power Station Clinch River Plant Bottom	Hutsonville Power Station	Hutsonville	IL	EPA Potential Damage Case	http://www.sourcewatch.or	http://carma.org/plant/d
Appalachian Power Co	American Electric Power	Ash Ponds	Clinch River Plant	Cleveland	VA	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	http://carma.org/plant/d
Appalachian Power Co	American Electric Power	Glen Lyn Plant Fly Ash Pond	Glen Lyn Plant	Glen Lyn	VA	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	http://carma.org/plant/d
Public Service Company of Oklamhoma	American Electric Power	Northeastern Station Bottom Ash Pond	Northeastern Station	Oologah	ОК	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	http://carma.org/plant/d
SWEPCO (Southwestern Electric		Flint Creek Power Plant						
Power Co)	American Electric Power	Primary Bottom Ash Pond Philip Sporn Power Plant Fly	Flint Creek Power Plant	Gentry	AR	EIP Damage Case - Aug 2010	http://www.sourcewatch.or	http://carma.org/plant/d
Appalachian Power Co	American Electric Power	Ash Pond Tanners Creek Plant Fly Ash	Philip Sporn Power Plant	New Haven	WV	EPA High Hazard Potential	http://www.sourcewatch.or	http://carma.org/plant/d
Indiana Michigan Power Co	American Electric Power	Pond	Tanners Creek Plant	Lawrenceburg	IN	EPA High Hazard Potential	http://www.sourcewatch.or	http://carma.org/plant/c
Kentucky Power Co	American Electric Power	Big Sandy Plant Fly Ash	Big Sandy Plant	Louisa	KY	EPA High Hazard Potential	http://www.sourcewatch.or	
Ohio Power Company	American Electric Power	General James M. Gavin Power Plant Fly Ash Pond	General James M.Gavin Power Plant	Cheshire	ОН	EPA High Hazard Potential, EIP D	http://www.sourcewatch.or	http://carma.org/plant/d
		Muskingum River Plant Unit		Waterford or				
Ohio Power Company	American Electric Power	5 Fly Ash Ponds Little Scary Creek Fly Ash	Muskingum River Plant	Beverly?	OH	EPA High Hazard Potential, EIP D		
Appalachian Power Co	American Electric Power	Impoundment	John Amos Plant	Winfield	WV	EPA High Hazard Potential, EIP D	Damage Case - Feb 2010	http://carma.org/plant/d
Ohio Power Company	American Electric Power	Mitchell Plant Fly Ash Pond Conesville Fixed FGD	Mitchell Generating Station	Moundsville	WV	EPA High Hazard Potential, EIP D	http://www.sourcewatch.or	http://carma.org/plant/c
Columbus Southern Power Company	American Electric Power	Sludge Landfill	Conesville Power Plant	Conesville	ОН	EPA Potential Damage Case	http://www.sourcewatch.or	g/index.php?title=Cones
Southwestern Electric Power Company Southwestern	American Electric Power	Welsh Reservoir	Welsh Plant	PITTSBURG	TX	EPA Proven Damage Case		http://carma.org/plant/d
Electric Power Company	American Electric Power	Brandy Branch Reservoir	Pirkey Power Plant	HALLSVILLE	TX	EPA Proven Damage Case		
	American Electric Power (43%),							
Ohio Valley Electric Corp/Indiana Kentucky Electric Corporation (IKEC)	FirstEnergy (11.5%), Duke (9%), E.ON (8%)	Clifty Creek West Boiler Slag Pond	Clifty Creek Station	Madison	IN	EIP Damage Case - Feb 2010	http://www.sourcewatch.or	http://carma.org/plant/c
	American Electric Power/Buckeye	Cardinal Plant Bottom Ash						
Cardinal Operating Co	Power	Complex	Cardinal Plant	Brilliant	OH	EIP Damage Case - Aug 2010, El	http://www.sourcewatch.or	http://carma.org/plant/d

		Apache Station Combustion					
Arizona Electric Pwr Coop Inc	Arizona's G&T Coops	Waste Disposal Facilities	Apache Generating Station	Cochise	AZ	EPA High Hazard Potential	http://www.sourcewatch.or http://carma.org/plant/d
Lower Colorado River Authority	Austin Energy (50% owner)	Fayette Power Project	_	La Grange	TX	EIP Damage Case - Aug 2010	http://www.sourcewatch.or http://carma.org/plant/d
Basin Electric Power Cooperative	Basin Electric Power Cooperative	Antelope Valley Station	Antelope Valley Station	Beulah	ND	EIP Damage Case - Aug 2010	http://www.sourcewatch.or http://carma.org/plant/d
		Leland Olds Station Coal					
Basin Electric Power Cooperative	Basin Electric Power Cooperative	Ash Disposal Ponds	Leland Olds Station	Stanton	ND	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.http://carma.org/plant/d
		W.J. Neal Station Surface					
Basin Electric Power Cooperative	Basin Electric Power Cooperative	Impoundment	W.J. Neal Station		ND	EPA Proven Damage Case	has been dismantled
Mid American Energy	Berkshire Hathaway	George Neal Station South	George Neal Station South	Salix	IA	EIP Damage Case - Aug 2010	http://www.sec.gov/Archivehttp://carma.org/plant/d
		George Neal Station North					
Mid American Energy	Berkshire Hathaway	Landfill	George Neal Station North	Sergeant Bluff	IA	EIP Damage Case - Aug 2010	http://www.sec.gov/Archivehttp://carma.org/plant/d
MidAmerican Energy	Berkshire Hathaway		Dave Johnston Power Plant	Glenrock	WY	EPA Potential Damage Case	http://www.sourcewatch.org/index.php?title=Dave_
		Coal Combustion ByProduct					
Bunge Milling, Inc.	Bunge	Disposal Site	Bunge Corporation's coal plant	Oakwood	IL	EIP Damage Case - Feb 2010	
Muscatine Power & Water	City of Muscatine, Iowa	Muscatine County Landfill	Muscatine Generating Station	Muscatine	IA	EPA Potential Damage Case	http://www.sourcewatch.org/index.php?title=Musca
		Curtis Stanton Coal					
		Combustion Waste (CCW)					
Orlando Utility Commission (OUC)	City of Orlando, Florida	Landfill and Ponds	Curtis Stanton Energy Center	Orlando	FL	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Cleco Power	Cleco Corp	Dolet Hills Power Station	Dolet Hills Power Station	Mansfield	LA	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.http://carma.org/plant/c
Cleco Power	Cleco Corp	Rodemacher Power Station	Rodemacher Power Station	Lena	LA	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.http://carma.org/plant/d
		J.R. Whiting Generating		L.			
Consumers Energy	CMS Energy	Plant	J.R. Whiting Generating Plant	Erie	MI	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Consumers Energy	CMS Energy	Karn and Weadock Landfills	Karn/Weadock Generating Facility	Essexville	MI	EIP Damage Case - Feb 2010	http://www.sourcewatch.or http://carma.org/plant/d
Dairyland Power Cooperative	Dairyland Power Cooperative	Alma On-site Fly Ash Landfill	Alma Station	Alma	WI	EPA Potential Damage Case	http://www.sourcewatch.or.http://carma.org/plant/d
		Salem Acres Site, Vitale					
		Brothers Fly Ash Pit and					
		K.R. Rezendes South Main					
Dominion Energy New England LLC	Dominion	Street Ash Landfill	Salem Harbor Station	Salem	MA	EPA Proven Damage Case	http://www.sourcewatch.org/index.php?title=Salerr
		Possum Point Ash Pond D &					
Virginia Electric Power Co	Dominion	E	Possum Point		VA	EPA Proven Damage Case	http://www.sourcewatch.or.coal generators retired
		Chisman Creek Disposal					
Virginia Power	Dominion	Site	Yorktown Power Station	Yorktown	VA	EPA Proven Damage Case	http://www.sourcewatch.org/index.php?title=Yorkto
		Stoneman Generating					
DTE Energy	DTE Energy	Station Ash Disposal Pond	E.J. Stoneman Generating Station		WI	EPA Proven Damage Case	http://www.sourcewatch.or.http://carma.org/plant/d
Duke Energy Indiana	Duke Energy	Gibson Generating Station	Gibson Generating Station	Princeton	IN	EIP Damage Case - Feb 2010	http://www.sourcewatch.or http://carma.org/plant/d
		Buck Primary and Secondary					
Duke Energy Carolinas	Duke Energy	Ponds	Buck Steam Station	Spencer	NC	EPA High Hazard Potential	http://www.sourcewatch.or.http://carma.org/plant/d
Duke Energy Carolinas	Duke Energy	Marshall Ash Pond	Marshall Steam Station	Terrell	NC	EPA High Hazard Potential	http://www.sourcewatch.or http://carma.org/plant/d
5 · F · O · I	- · -	Riverbend Primary and	D. 1 10: 0: 1				
Duke Energy Carolinas	Duke Energy	Secondary Ponds	Riverbend Steam Station	Mount Holly	NC	EPA High Hazard Potential	http://www.sourcewatch.or http://carma.org/plant/d
Dalla Farana Orașilia a	Data Farana	Dan River Primary and	Day Diver Ota and Otation	E 4	NO	EDA Historia Devential EID	
Duke Energy Carolinas	Duke Energy	Secondary Ponds	Dan River Steam Station	Eden	NC	EPA High Hazard Potential, EIP L	http://www.sourcewatch.or.http://carma.org/plant/d
Duka Faarru Caralinaa	Pulsa Francia	Belews Creek Steam Station	Dalawa Casali Stanes Statis	Dalaura Crasti	NC	EDA High Hammy Detantist SID 5	http://www.accompanies.com/
Duke Energy Carolinas	Duke Energy	Landfills	Belews Creek Steam Station	Belews Creek	NC	EPA High Hazard Potential, EIP L	http://www.sourcewatch.or.http://carma.org/plant/d
Duka Faarru Caralinaa	Dules France	G.G. Allen Steam Plant Ash	C C Aller Steem Blant	Dalmant	NC	EDA High Hannel Detantist EDA	http://www.co.wco.wctch.com/http://come
Duke Energy Carolinas	Duke Energy	Pond	G.G. Allen Steam Plant	Belmont	NC	EPA HIGH HAZARO POTENTIAI, EPA	http://www.sourcewatch.or.http://carma.org/plant/d
Cinoray	Duke Energy	East Bend Scrubber Sludge	Fact Bond Congreting Station	Linian	KY	EBA Retential Damage Coop	http://www.courcewatch.or.http://corrections/
Cinergy	Duke Energy	Landfill W.C. Bookierd Station	East Bend Generating Station	Union New Biohmand	OH	EPA Potential Damage Case	http://www.sourcewatch.or.http://carma.org/plant/d
Cinergy Duko Eporgy	Duke Energy Duke Energy	W.C. Beckjord Station Belews Lake	W.C. Beckjord Station	New Richmond	NC	EPA Potential Damage Case EPA Proven Damage Case	http://www.sourcewatch.or/http://carma.org/plant/d
Duke Energy	Duke Energy	Delews Lake	Belews Creek Steam Station	Belews Creek	INC	EFA Floven Damage CaSe	http://www.sourcewatch.org/index.php?title=Belew
Duguespe Light Co	Duguesno Light Co	Phillips Power Plant Landfill	Phillips Power Plant (no longer in operation)	South Haighta	PA	EIP Damage Case - Feb 2010	
Duquesne Light Co.	Duquesne Light Co.	Havana Power Plant Ash	operation)	South Heights	FA	LIF Dalliage Case - Feb 2010	
Dynagy Midwest Congration Inc.	Dynegy	Pond System	Havana Power Station	Havana	IL	EPA High Hazard Potential	http://www.sourcewatch.or.http://carma.org/plant/d
Dynegy Midwest Generation Inc Dynegy Midwest Generation Inc	Dynegy Dynegy	Wood River East Ash Pond	Wood River Station	Alton	IL IL	EPA High Hazard Potential	http://www.sourcewatch.or.http://carma.org/plant/d
Dynegy Mildwest Generation Inc	Dynegy	Hennepin Power Station Ash		AIIOH	IL	LEA HIGH HAZARU POLEHILIAI	mtp.//www.sourcewatch.ormtp.//carma.org/plant/c
□ Dynegy Midwest Generation	Dynogy	Pond System	Hennepin Power Station	Hennepin	IL	EPA Potential Damage Case	http://www.sourcewatch.or.http://carma.org/plant/d
□ Dynegy iviluwest Generation	Dynegy	Vermilion Power Station Ash	nemepin rower Station	i ieririepin	IL.	LEA FULERILIAI DAMAGE CASE	mtp://www.sourcewatch.ornttp://carma.org/plant/c
□ Dynegy Midwest Generation	Dynogy	Ponds	Vermilion Power Station	Oakwood	IL	EPA Potential Damage Case	http://www.sourcewatch.or.http://carma.org/plant/d
I - Dynedy iviidwest Generation	Dynegy	r unus	verminon rower station	Oakwood	I IL	LEA FOIEIIIIAI Damage Case	mup.//www.sourcewatch.ormup.//cama.org/plant/o

		Wood River Power Station					1	
☐ Dynegy Midwest Generation	Dynegy	Ash Ponds	Wood River Power Station	Alton	IL	EPA Potential Damage Case	http://www.sourcewatch.or.htt	to://carma.org/plant/d
= 2) nogy marroet contraction		Danskammer Waste	Danskammer Generating Station	,		2.711 Stormar Barriage Gase	map.,, miniscarco materilo in	ip://odima.org/plant/o
Dynegy	Dynegy	Management Facility	(Roseton Generating Station)	NEWBURGH	NY	EPA Potential Damage Case	http://sourcewatch.org/indeht	to://carma.org/plant/d
Louisville Gas and Electric	E.ON	Mill Creek Station Landfills	Mill Creek Station	Louisville	KY	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.htt	
		E W Brown Ash and						
Kentucky Utilities Co	E.ON	Auxiliary Ponds	E.W. Brown Generating Station	Harrodsburg	KY	EPA High Hazard Potential	http://www.sourcewatch.or.htm	tp://carma.org/plant/d
,		Ghent Gypsum Stacking		Ü		, and the second	i	
Kentucky Utilities Co	E.ON	Facility and Ash Ponds	Ghent Generating Station	Ghent	KY	EPA High Hazard Potential	http://www.sourcewatch.or.htm	tp://carma.org/plant/d
Louisville Gas & Electric Co	E.ON	Cane Run Ash Pond	Cane Run Station	Louisville	KY	EPA High Hazard Potential	http://www.sourcewatch.or.htm	
		Spurlock Power Station				, and the second		
East Kentucky Power Coorperative	East Kentucky Power Coorperative	Landfill	Spurlock Power Station	Maysville	KY	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.htm	tp://carma.org/plant/d
·								
Midwest Generations EME LLC	Edison International	Lincoln Stone Quarry Landfill	Joliet 9 Generating Station	Joliet	IL	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.htt	tp://carma.org/plant/d
Midwest Generation EME	Edison International	Mahoney Landfill	Powerton Plant	PEKIN	IL	EPA Potential Damage Case	http://www.sourcewatch.or.htt	tp://carma.org/plant/c
		Independence Steam						
		Station Ash Landfill and						
Arkansas Power and Light	Entergy	Ponds	Independence Steam Station	Newark	AR	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.htt	
FirstEnergy Generation Corp.	FirstEnergy Corp.	Little Blue Run Dam	Bruce Mansfield Power Station	Shippingport	PA	EPA High Hazard Potential; EIP D	http://www.sourcewatch.or.htt	tp://carma.org/plant/d
		Coal Creek Surface						
Great River Energy	Great River Energy	Impoundments	Coal Creek Station	Underwood,	ND	EPA Proven Damage Case	http://www.sourcewatch.or.htt	tp://carma.org/plant/c
		Merom Generating Station						
Hoosier Energy Rural Electric	Hoosier Energy Rural Electric	Coal Combustion Waste						
Cooperative	Cooperative	Landfill	Merom Generating Station	Merom	IN	EPA Potential Damage Case	http://www.sourcewatch.or.htt	tp://carma.org/plant/d
Hyman Budoff/Merle and Charles	Hyman Budoff/Merle and Charles	Industrial Excess Landfill	Akron and Canton area boilers in					
Kittinger	Kittinger	Superfund Site	the 1960s	Uniontown	OH	EIP Damage Case - Aug 2010		
		C.D. McIntosh, Jr. Power						
Lakeland Electric	Lakeland Electric	Plant	C.D. McIntosh, Jr. Power Plant	Lakeland	FL	EIP Damage Case - Aug 2010	http://www.lakelandelectricht	tp://carma.org/plant/c
			Lansing Board of Water and Light					
			(LBWL) electric and steam					
Lansing Board of Water & Light	Lansing Board of Water & Light	North Lansing Landfill	generating plants (1980-1997)	Lansing	MI	EPA Proven Damage Case		
	Manitowoc Public Utilities (owns							
Lemberger Landfill, Inc. (owns landfill)	power plant)	Lemberger Landfill	Manitowoc Public Utilities	WHITELAW	WI	EPA Potential Damage Case		
Montana-Dakota Utilities	MDU Resources Group	R.M. Heskett Station		Mandan	ND	EPA Potential Damage Case	http://www.sourcewatch.or.htt	tp://carma.org/plant/c
		Faulkner Off-site Disposal						
Mirant	Mirant	Facility	Morgantown Generating Station	Faulkner	MD	EPA Proven Damage Case	http://www.sourcewatch.or.htt	tp://carma.org/plant/d
Mirant MD Ash Management, LLC /	L.,	Brandywine Coal Ash					l	
Mirant Mid-Atlantic, LLC	Mirant Corporation	Landfill	Chalk Point Point Power Plant	Brandywine	MD	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.htt	tp://carma.org/plant/c
				TONIANA N.D.A		554.5 4 44.5		
National Grid	National Grid	C. R. Huntley Flyash Landfill	Huntley Steam Generating Station	TONAWANDA	NY	EPA Potential Damage Case		
Northern Indiana Public Service	NIO	Michigan City Site Ash	Miletines Oir Oir	Mishissa Oite	18.1	EDA Detectiel Decree Occor	hatta tha and a same and a harm	and a superior of the Court of
Company	NiSource	Ponds	Michigan City Site	Michigan City	IN	EPA Potential Damage Case	http://www.sourcewatch.org/ii	naex.pnp?titie=iviicniç
Northern Indiana Public Service	NiCarras	Bailly Generating Station	Dailly Consenting Station	Chastantan	INI	EDA Detectial Demana Cons	http://www.commonwetch.com/i	aday abaQtitla Dailly
Company	NiSource	Ash Disposal Ponds R.M. Schahfer Generating	Bailly Generating Station	Chesterton	IN	EPA Potential Damage Case	http://www.sourcewatch.org/ii	ndex.pnp?titie=Bailiy_
Northern Indiana Public Service	NiCarman		D.M. Cababéas Casasatias Station	Wheethald	INI	EDA Detectiol Democra Cons	http://www.aavaaavatah.aaa/i	adau abaûida Cabab
Company Northern Indiana Public Service Corp.	NiSource	Station Brown's Yard 520 Landfill	R.M. Schahfer Generating Station Bailly and Michigan City Power	Wheatfield	IN	EPA Potential Damage Case	http://www.sourcewatch.org/ii	nuex.pnp:nne=ochar
(NIPSCO)	NiSource Inc.	Site	Plants	Pines	IN	EPA Proven Damage Case	http://www.sourcewatch.or.htt	to://carma.org/plant/a
Louisiana Generating	NRG Energy	Big Cajun 2 Ash Ponds	Big Cajun 2 Power Plant	New Roads	LA	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.ht	
Louisiana Generaling	INC LIIEIGY	Montville On-site and Off-site		IACM I/OGUS	LA	Lii Damaye Case - Aug 2010	mtp.//www.sourcewatch.ornt	φ.//carria.org/piarit/0
		Ash Storage and Disposal	1					
Montville Power, LLC	NRG Energy	Areas	Montville Generating Station	Uncasville	СТ	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.htt	tn://carma.org/plant/d
NRG Energy	NRG Energy	Burton Island Ash Landfill	Indian River Generating Station	Millsboro	DE	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.ht	
RRI Energy, Inc (landfill), Reliant		Fern Valley Coal	main rayor contraining Station			E. Barrage Gade 1 cb 2010		p.,, carria.org/piarit/c
(power plant)	NRG Energy	Combustion Waste Landfill	Elrama Power Plant (1989 - 2003)	Firama	PA	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.htt	to://carma.org/plant/d
April 5 pany		2 3 Daoilott Tradio Eariailli						
Don Frame Trucking, Inc. (owns landfil	NRG Energy (owns nower plant)	Fly Ash Landfill	Dunkirk Steam Station	FREDONIA	NY	EPA Proven Damage Case		
NV Energy	NV Energy	Reid Gardener Ash Ponds	Reid Gardner Station	Moapa	NV	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.htt	tp://carma.org/plant/d
3/		Big Stone Coal Combustion						,
		Waste (CCW) Disposal						
		Units, Ponds, and						
Otter Tail Power	Otter Tail Power	Impoundments	Big Stone Power Plant	Big Stone City	SD	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.htm	tp://www.sourcewatcl
	•							

An impoundment of the process			Four Corners Power Plant			1		
Column Primary Column	Arizona Public Service	Pinnacle West Capital Corp		Four Corners Power Plant	Fruitland	NM	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Portand General Electric Portand General Elect								
Combuster Water (CAM) Per Montand General Electric Per Montand General Ele	7 (Hzoria i abilo corvico	i iiiiadid ii dat dapitai da b		Crisia Coristaning Station	оссори ску	7.1	2.71 ngm mazara r otomian, 2.71	mp,, rumicourou atomol mp,, camaio, gipiana
Douglast Electric Disposed Areas and Units Department D								
PPL Mortrang, LLC PPL Control Finance Country Forms Finance Country Finance Coun	Portland General Electric	Portland General Electric		Boardman Plant	Boardman	OR	EIP Damage Case - Aug 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Pep. Morris LLC Progress Energy South Improvement of the Control S								
South Seam Plant Call Administration of the Progress Energy Approach	PPL Montana, LLC	PPL		Colstrip Power Plant	Colstrip	мт	EPA High Hazard Potential, EIP D	http://www.sourcewatch.or.http://carma.org/plant/d
Progress Energy An Impoundment Lee Steam Plant Lee Ste								
Pogress Energy (acclinis Inc. Pogress Energy Pood Albert (acclinis Inc. Pool Inc. Politic Inc. Popress Energy Pood Inc. Politic	Progress Energy Carolinas Inc.	Progress Energy		Sutton Steam Plant	Wilmington	NC	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Progress Energy Progress Energ	3,	3			J		3	3
Cape Feer Steam Plant	Progress Energy Carolinas Inc.	Progress Energy		Lee Steam Plant	Goldsboro	NC	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Progress Energy Impoundments Cape Fee Steam Plant Moncaye No. EP Darrage Case - Feb 2010 Nation/www.sourcewatch of http://cama.org/plants/capes.persy.	The state of the s	, regrees and gy						3,
Asheville 1982 Pord 4: 1992 Pord 4: 1994 Asheville 1982 Pord 4: 1994 Pord 4: 1994 Asheville 1982 Pord 4: 1994 Pord 4: 1	Progress Energy Carolinas Inc.	Progress Energy	Impoundments	Cape Fear Steam Plant	Moncure	NC	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Progress Energy Productions in Progress Energy Production Progress Energy Progress Ener			Asheville 1982 Pond & 1964					
Progress Energy Progress Energy Progress Energy Progress Energy Progress Energy	Progress Energy Carolinas Inc	Progress Energy		Asheville Steam Electric Plant	Arden	NC	EIP Damage Case - Feb 2010; EF	http://www.sourcewatch.or.http://carma.org/plant/d
Elemen Plate Technology, Inc., Full Circle Selds Technology, Inc., Full Circle Selds Technology, Inc., Full Circle Selds Technology, Inc., Full Selds Technology, Inc.,	Progress Energy		Hyco Lake	Roxboro Steam Electric Plant	SEMORA	NC		
Reliber Technology, Inc. / Full Circle Solutions, Inc. Reliber Technology, Inc. / Full Circle Solutions, Inc. Reliber Technology, Inc. / Full Circle Solutions, Inc. Reliber Technology, Inc. Relibe	Orion Power Holdings Inc.			Elrama Plant	Elrama	PA	EPA Potential Damage Case	http://www.sourcewatch.org/index.php?title=Elram
Selutions, Inc. Selito Solutions, Inc. Selito Seward Generaling Station Coal Act and Relate Pt Seward Generaling Station Seward G			Swift Creek Structural Fill	Six North Carolina and Virginia			· ·	Ĭ
RR Energy, Inc. Rel Energy	Solutions, Inc.	Circle Solutions, Inc.	site	power plants	Rocky Mount	NC	EIP Damage Case - Feb 2010	
RI Energy, Inc. RR Energy, Inc. RR Energy, Inc. RR Energy, Inc. Sate Portland Generating Station South Carolina Electric & Cooper Fly Ash Ponds and Carolina Electric & Cooperative Scanda Caroparation Londill and Setting Basins Longular Station Coal Ash Disposal Case (Linguistic Service Authority) SCEAN Corporation Longular Station Coal Ash Disposal Case (Linguistic Service Authority) SCEAN Corporation Longular Station Coal Ash Disposal Case (Linguistic Coaperative Service Authority) SCANA Corporation Longular Station Longular Station Longular Station Longular Station SCEAN Corporation Longular Station SCEAN Corporation Longular Station Scenific Carolina Electric & Gas SCANA Corporation Longular Ash Storage Pond Canadys Plant Canady			Seward Generating Station					
RI Energy, Inc. RR Energy, Inc. RR Energy, Inc. RR Energy, Inc. Sate Portland Generating Station South Carolina Electric & Cooper Fly Ash Ponds and Carolina Electric & Cooperative Scanda Caroparation Londill and Setting Basins Longular Station Coal Ash Disposal Case (Linguistic Service Authority) SCEAN Corporation Longular Station Coal Ash Disposal Case (Linguistic Service Authority) SCEAN Corporation Longular Station Coal Ash Disposal Case (Linguistic Coaperative Service Authority) SCANA Corporation Longular Station Longular Station Longular Station Longular Station SCEAN Corporation Longular Station SCEAN Corporation Longular Station Scenific Carolina Electric & Gas SCANA Corporation Longular Ash Storage Pond Canadys Plant Canady	RRI Energy, Inc.	RRI Energy, Inc.		Seward Generating Station	New Florence	PA	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
RRI Energy, Inc. Rri Energy Generating Station Fly Ash Ponds Landill and Settling Beains Landill and Settling Beains RRI Energy, Inc. RRI Energy, Inc. Renerating Station Landill and Settling Beains RRI Energy, Inc. RRI Energy, Inc. Renerating Station Renerat		3 .		Ĭ				
Scent Cooper (F) Ash Ponch (Service Authority) Santee Cooper (F) Ash Ponch (Service Authority) Schol Carolina Electric & Gas Schol Carolina Electric & Gas Schol Corporation Urquhart Station Coal Ash (Jacquart River O-Area (Jacqua	RRI Energy, Inc.	RRI Energy, Inc.		Portland Generating Station's	Bangor	PA	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
South Carolina Electric & Gas CANA Corporation SCANA Corporation SCANA Corporation Wateree Coal Ash Landilli and Setting Basins Wateree Station SCANA Corporation Wateree Station SCANA Corporation	South Carolina Public Service Authority		Grainger Generating Station	· ·	Ĭ		Ĭ	
South Carolina Electric & Gas Company (SEAS) SCANA Corporation Landilli and Setting Basins Urquhart Station Beach Island SC EIP Damage Case - Feb 2010 http://www.sourcewatch.org/inde/plant/scana.org/plant	(SCPSA)	Santee Cooper	Fly Ash Ponds	Grainger Generating Station	Conway	SC	EIP Damage Case - Feb 2010	http://www.sourcewatch.or http://www.sourcewatcl
South Carolina Electric and Gas SCANA Corporation Scannah River D-Area Department of Energy SCANA Corporation South Carolina Electric & Gas SCANA Corporation Scannah River D-Area D-	South Carolina Electric & Gas		Urquhart Station Coal Ash					
South Caropiration Scanna River D-Area Department of Energy SCANA Corporation Scanna River D-Area Department of Energy SCANA Corporation Scanna River D-Area Department of Energy SCANA Corporation Scanna River D-Area D-A	Company (SGE&G)	SCANA Corporation	Landfill and Settling Basins	Urquhart Station	Beech Island	SC	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Savannah River D'Area Department of Energy SCANA Corporation South Carolina Electric & Gas SCANA Corporation Seminole Electric Cooperative Southern Company Plant Branch E Harfiee Branch Generating Station Southern Company Lansing Smith Plant Southern Company Southern Company Power Southern Company Southern Company Power Southern Company Power Southern Company Power Southern Company Power Southern Elinois Power Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Marion Plant Landfills and Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Marion Plant Landfills and Cooperative Southern Illinois Power Marion Plant Landfills and Marion Plant Marion IL EIP Damage Case - Aug 2010 http://www.sourcewatch.or/pindex.php?title=Shaw Interviews.orucewatch.org/pindex.php?title=Shaw Interviews.orucewatch.org/pindex.php?title=Shaw Interviews.orucewatch.org/pindex.php?title=Shaw Interviews.orucewatch.org/pindex.php?title=Shaw Interviews.orucewatch.org/pindex.php?title=	South Carolina Electric and Gas		Wateree Coal Ash					
Seavanah Froject Aiken SC EPA Proven Damage Case http://sourcewatch.org/inde/http://carma.org/plant/carma.org/	(SCE&G)	SCANA Corporation	Impoundment	Wateree Station	Eastover	SC	EIP Damage Case - Feb 2010	http://www.sourcewatch.or.http://carma.org/plant/d
Seavanah Froject Aiken SC EPA Proven Damage Case http://sourcewatch.org/inde/http://carma.org/plant/carma.org/			Savannah River D-Area					
Scan Canady Plant Carolina Electric & Gas SCANA Corporation Pond Scandy Plant Canadys	Department of Energy	SCANA Corporation		Savannah River Project	Aiken	SC	EPA Proven Damage Case	http://sourcewatch.org/indehttp://carma.org/plant/d
Seminole Electric Cooperative Seminole Electric Cooperative Southern Company Southern Company Lansing Smith Plant Southern Company Pond Bowen Steam Plant Ash Pond Southern Illinois Power Southern Illinois			Canadys Plant Ash Storage					
Seminole Electric Cooperative Seminole Electric Cooperative Southern Company Southern Company Plant Branch E Aufille Branch Generating Plant Southern Company Lansing Smith Plant Southern Company Bowen Steam Plant Ash Pond Southern Illnois Power Souther	South Carolina Electric & Gas	SCANA Corporation	Pond	Canadys Plant	CANADYS	SC	EPA Proven Damage Case	http://www.sourcewatch.or http://carma.org/plant/d
Seminole Electric Cooperative Seminole Electric Cooperative Southern Company Plant Branch E Harfiele Branch Generating Plant Milledgeville GA EPA High Hazard Potential Introversional Plant Southern Company Dent Southern Company Lansing Smith Plant Sanch E Harfiele Branch Generating Plant Milledgeville GA EPA Provential Introversional Plant Southern Company Southern Company Dend Southern Company Pond Bowen Steam Plant Ash Pond Southern Illinois Power Cooperative Ponds Marion Plant Landfills and Cooperative Ponds Marion Plant Landfills and Southern Illinois Power Cooperative Ponds Marion Plant Landfills and Southern Illinois Power Ponds Marion Plant Landfills and Ponds Southern Illinois Power Cooperative Ponds Marion Plant Landfills and Ponds Sheldon Station Coal Ash III Sheldon Station Plant Sheldon Sheldo			Seminole Generating Station					
Southern Company Plant Branch E Harflee Branch Generating Plant Southprort Southprort Company Plant Branch E Harflee Branch Generating Plant Southprort E EPA Protential Damage Case http://www.sourcewatch.orlitp://carma.org/plant/c Southprort E EPA Proven Damage Case http://www.sourcewatch.orlitp://carma.org/plant/c EPA Damage Case http://www.sourcewatch.orlitp://carma.org/plant/c EPA Damage Case http://www.sourcewatch.org/index.php?title=Sig_E EPA Damage Case http://www.sourcewatch.org/index.php?title=Sig_E EPA Damage Case http://www.sourcewatch.org/index.php?title=Sig_E EPA Damage Case http://www.sourcewatch.org/index.php?title=Sig_E EPA Damage Case http://www.sourcewatch.org/index.php?title=Cumb http://www.sourcewatch.org/index.php?title=Cumb http://www.sourcewatch.org/index.php?title=Sig_E EPA Damage Case http://www.sourcewatch.org/index.php?title=Sig_E EPA Damage Case http://www.sourcewatch.org/index.php?title=Sig_E EPA Damage Case http://www.sourcewatch.org/index.php?ti			Wastewater Ponds and					
Southern Company Southern Illinois Power Cooperative Southern Illinois Power Cooperative Southern Illinois Power Long Polantic Southern Illi	Seminole Electric Cooperative	Seminole Electric Cooperative			Palatka	FL		http://www.sourcewatch.or http://carma.org/plant/d
Bowen Steam Plant Ash Bowen Steam Plant Bowen Steam Plant Ash Ponds Marion Plant Landfills and Ponds Marion Plant Landfills and Ponds Marion Plant Landfills and Ponds Marion Plant Marion II. EIP Damage Case - Aug 2010 http://www.sourcewatch.or/.nhttp://carma.org/plant/c Power District State of Nebraska #3 Sheldon Station Coal Ash Plt Sheldon Station Big Bend Station Apollo Beach FL EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Big Bends Plant Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Shaw Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Cumberland Steam Plant City Th EIP Damage	Georgia Power			Harllee Branch Generating Plant				
Southern Company Pond Bowen Steam Plant Cartersville GA EPA Proven Damage Case http://www.sourcewatch.or/ http://carma.org/plant/company	Gulf Power	Southern Company			Southport	FL	EPA Potential Damage Case	http://www.sourcewatch.or http://carma.org/plant/d
Southern Illinois Power Cooperative Cooper								
Southern Illinois Power Cooperative Cooperative Ponds Marion Plant Marion IL EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Bulls Plants Plant Sheldon Station Plant Marion IL EIP Damage Case - Aug 2010 http://www.sourcewatch.org/index.php?title=Bulls Plants Plant Plants Pl	Georgia Power			Bowen Steam Plant	Cartersville	GA	EPA Proven Damage Case	http://www.sourcewatch.or http://carma.org/plant/d
Sheldon Station Coal Ash Pit #3 Sheldon Station Coal Ash Pit #43 Sheldon Station Make properties with the properties of		Southern Illinois Power	Marion Plant Landfills and					
State of Nebraska	Southern Illinois Power Cooperative	Cooperative		Marion Plant	Marion	IL	EIP Damage Case - Aug 2010	
TECO Energy Big Bend Station Big Bend Station Apollo Beach FL EIP Damage Case - Feb 2010 http://www.sourcewatch.org/index.php?title=Big_B Fennessee Valley Authority Tennessee Valley A	L				L	l .		
Tennessee Valley Authority Tennessee Valley Auth	Nebraska Public Power District							
Tennessee Valley Authority Tennessee Valley Auth	Tampa Electric Company							
Tennessee Valley Authority Tennessee Valley Auth	Tennessee Valley Authority	Tennessee Valley Authority	Shawnee Fossil Plant	Shawnee Fossil Plant		KY	EIP Damage Case - Aug 2010	http://www.sourcewatch.org/index.php?title=Shaw
Tennessee Valley Authority Colbert Fossil Plant New Now New Tennessee Valley Authority Tennessee Valley Authority Stick Widows Creek Stevenson AL EPA High Hazard Potential http://www.sourcewatch.org/index.php?title=Bull_F Cumberland City TN EPA High Hazard Potential http://www.sourcewatch.org/index.php?title=Colbe http://www.sourcewatch.org/index.php?title=Colbe http://www.sourcewatch.org/index.php?title=Colbe http://www.sourcewatch.org/index.php?title=Colbe						l		
Tennessee Valley Authority Tennessee Valley Auth	Tennessee Valley Authority							
Tennessee Valley Authority Tennessee Valley Auth	Tennessee Valley Authority	Tennessee Valley Authority	Gallatin Fossil Plant	Gallatin Fossil Plant		TN	EIP Damage Case - Aug 2010	http://www.sourcewatch.org/index.php?title=Gallat
Tennessee Valley Authority Tennessee Valley Authority Tennessee Valley Authority John Sevier Fossil Plant Widows Creek Gypsum Stack Widows Creek Bull Run Fly Ash Pond and Stilling Basin Area 2 Cumberland Ash Pond & Cumberland Ash Pond & Cumberland Ash Pond Ash Tennessee Valley Authority Ten								
Fennessee Valley Authority Tennessee Valley Authority Te	Tennessee Valley Authority							
Tennessee Valley Authority Tennessee Valley Authority Stack Widows Creek Stevenson AL EPA High Hazard Potential http://www.sourcewatch.org/index.php?title=Widow Tennessee Valley Authority Tennessee Valley Autho	Tennessee Valley Authority	Tennessee Valley Authority		John Sevier Fossil Plant	Rogersville	TN	EIP Damage Case - Feb 2010	http://www.sourcewatch.org/index.php?title=John_
Bull Run Fly Ash Pond and Stilling Basin Area 2 Cumberland Ash Pond & Cumberland Cinton Tournessee Valley Authority Tennessee Valley Author				L		l		
Tennessee Valley Authority Tennessee Valley Authority Stilling Basin Area 2 Bull Run Clinton TN EPA High Hazard Potential http://www.sourcewatch.org/index.php?title=Bull_F Cumberland Ash Pond & Cumberland City Tnnessee Valley Authority Tennessee Valley Authority Tennessee Valley Authority Tennessee Valley Authority Colbert Plant Ash Pond 4 Colbert Fossil Fuel Plant Tuscumbia Tennessee Valley Authority Tennessee Valley Authority (owns Tennessee Valley Authority (owns) Tennessee Valley Authority (owns) Tennessee Valley Authority (owns)	Tennessee Valley Authority	Tennessee Valley Authority		Widows Creek	Stevenson	AL	EPA High Hazard Potential	http://www.sourcewatch.org/index.php?title=Widov
Cumberland Ash Pond & Cumberland City TN EPA High Hazard Potential http://www.sourcewatch.org/index.php?title=Cumb Tennessee Valley Authority Tennessee Valley Authority Colbert Plant Ash Pond 4 Colbert Fossil Fuel Plant Tennessee Valley Authority (owns Tennessee Valley Authority (owns) Tennessee Valley Authority (owns) Tennessee Valley Authority (owns)	L	L		L	L	l		
Tennessee Valley Authority Tennessee Valley Authority Gypsum Storage Area Cumberland City TN EPA High Hazard Potential http://www.sourcewatch.org/index.php?title=Cumb Tennessee Valley Authority Tennessee Valley Authority Tennessee Valley Authority (owns Tennessee Valley Authority (owns) Tennessee Valley Authority (owns)	I ennessee Valley Authority	Tennessee Valley Authority		Bull Run		ΪN	EPA High Hazard Potential	http://www.sourcewatch.org/index.php?title=Bull_F
Tennessee Valley Authority (owns		L					l-p	
Tennessee Valley Authority (owns					1 7			
	Tennessee Valley Authority		Colbert Plant Ash Pond 4	Colbert Fossil Fuel Plant	Tuscumbia	AL	EPA Potential Damage Case	http://www.sourcewatch.org/index.php?title=Colbe
rans-Ash, inc (owns landfill) power plant) ICCW Landfill Johnsonville Fossil Plant Camden TN ElP Damage Case - Feb 2010 http://www.sourcewatch.org/index.php?title=Johns			00111	l.,				
	i rans-Ash, inc (owns landfill)	power plant)	CCVV Landfill	Jonnsonville Fossil Plant	Camden	ΙN	EIP Damage Case - Feb 2010	Inττp://www.sourcewatch.org/index.php?title=Johns

UGI Development Company	UGI Corporation	UGI Hunlock Power Station	UGI Hunlock Power Station	Hunlock Creek	PA	EIP Damage Case - Feb 2010	http://www.sourcewatch.org/index.php?title=Hunlo
Southern Indiana Gas and Electric		A.B Brown Generating					
Company (SIGECO)	Vectren	Station	A.B Brown Generating Station	Mount Vernon	IN	EPA Potential Damage Case	http://www.sourcewatch.org/index.php?title=AB.
		Caledonia, Oak Creek					
		South, and Oak Creek North					
Wisconsin Electric Power Co	Wisconsin Energy Corporation	Coal Ash Landfills	Oak Creek Power Plant	Oak Creek	WI	EIP Damage Case - Aug 2010	http://www.sourcewatch.org/index.php?title=South
				Town of			
Wisconsin Electric Power Co	Wisconsin Energy Corporation	Highway 59 Landfill		Waukesha	WI	EPA Proven Damage Case	
				Town of			
Wisconsin Electric Power Co	Wisconsin Energy Corporation	Cedar-Sauk Landfill	Port Washington Power Plant	Cedarburg	WI	EPA Proven Damage Case	
		Port Washington Fly Ash					
Wisconsin Electric Power Co	Wisconsin Energy Corporation	Pond	Port Washington Facility		WI	EPA Proven Damage Case	
Southern Minnesota Municipal Power		Sherburne County (Sherco)	Sherburne County (Sherco)				
Agency	Xcel Energy	Generating Plant Becker	Generating Plant Becker	Becker	MN	EPA Potential Damage Case	http://www.sourcewatch.org/index.php?title=Shert